MCR SAFETY CUT PRO

Washing Instructions: HPPE Gloves

Gloves containing HPPE should be washed with the following instructions to avoid shrinkage and prolong the life of the gloves.

1. Use commercial laundry soap or detergent that does not contain chlorine-based chemicals, bleach, or dry-cleaning solutions. Oxi-clean or equivalent is the preferred detergent to avoid shrinkage of HPPE gloves.
2. Machine wash in warm-hot water up to 194°F. Recommended to wash at 140°F for 15 minutes for optimal results. Gloves should be machine washed at 203°F if coming into contact with food.
3. Rinse in warm-hot water up to 194°F. Recommended to rinse at 140°F for 15 minutes for optimal results. Gloves should be rinsed at 203°F when coming into contact with food.
4. Recommended tumble dry at 131°F for 15 minutes for optimal results. Gloves should be placed in a tumble dryer at 140°F if coming into contact with food.
5. Repeat wash and rinse if gloves contain heavy dirt or grease. You may use several pieces of heavy canvas/cotton in the second wash to help remove deep grime from the gloves.

Please note that HPPE gloves have a melting point of 290-306°F. Conventional laundering is recommended up to 194°F to maximize use of HPPE gloves unless coming into contact with food which should utilize slightly higher temperatures.



MCR SAFETY

800-955-6887 | www.mcrsafety.com