MCR SAFETY CUT PRO

Washing Instructions: Hypermax™ Gloves

HYPERMAX

Gloves and sleeves containing Hypermax™ should be washed with the following instructions to avoid shrinkage and prolong the life of the gloves.

1. Use commercial laundry soap or detergent that does not contain chlorine-based chemicals, bleach, or dry cleaning solutions. Oxi-clean or equivalent is the preferred detergent to avoid shrinkage of Hypermax™ gloves.
2. Machine wash in warm-hot water up to 194°F. Recommended to wash at 140°F for 15 minutes for optimal results.
3. Rinse in warm-hot water up to 194°F. Recommended to rinse at 140°F for 15 minutes for optimal results.
4. Recommended tumble dry at 131°F for 15 minutes for optimal results.
5. Repeat wash and rinse if gloves contain heavy dirt or grease. You may use several pieces of heavy canvas/cotton in the second wash to help remove deep grime from the gloves.

Please note that Hypermax™ gloves have a melting point of 290-306°F. Conventional laundering is recommended up to 194°F to maximize use of Hypermax™ gloves. These gloves are not intended for direct food contact.

MCR SAFETY

800-955-6887 | www.mcrsafety.com